

W 464-0208

ARD REPORT on the

M.S. "Nora Maersk"

It is submitted the Copenhagen Surveyors be requested to forward two copies of the midship section and general arrangement plans of the above vessel & They should ~~also~~ ^{as required by Circular 1483,} state the bearing surface of the webs of Nos 1 and 2 hatchways on the superstructure deck, and verify the bearing surface of the webs of Nos 1, 2, 3, 4 & 5 hatchways on the foreboard deck (reported by them as being 70 m.p.) as this is required to be 75 m.p. by Rule XI¹ of the Convention. They should also state if the running hatchways on the foreboard deck are fitted with tarpaulins, cleats & battens, giving particulars thereof.

 Lloyd's Register
 Foundation
 87.B. 13.7.34