

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19 When handed in at Local Office 17. 8. 36 Port of Glasgow  
No. in Reg. Book Survey held at Bowling Date, First Survey 4 Last Survey 11. Aug 1936  
(No. of Visits 1)  
72286 on the Wood, Iron or Steel S. S. "CAIRNGORM"  
TONNAGE: Built at Glasgow By whom J. Shearer & Sons When 1904 MONTH 4  
GROSS #01 Owners Wm Robertson Owners' Address (if not already recorded in Appendix to Register Book)  
UNDER DK. 281 Managers Port belonging to Glasgow  
NET 156

Surveyed Afloat or in Dry Dock? On slip Name of Dock Scott & Sons Destined Voyage Laid up

=CellDBorDBa feet; uE&B feet; f feet  
Capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

st Report, No. 57044 Port Gls

Special Surveys, when held, must be reported in detail and scrutiny in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he rendered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER, &c. for Special Survey. Date of last survey and of Periodical Surveys.	Year Assigned or expired.	Machinery and Boiler surveys (including date of N.B., if any).
+ 100 A1		+ LMC 6.32
6.34		B 5.5.36
S.S. Burg 2 <sup>nd</sup> N <sup>o</sup> 3-12.23		CL 12.32
S.S. Oyt N <sup>o</sup> 2-32		

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR

Docking.

Vessel placed on slip, bottom, keel & rudder examined & found satisfactory. Decks, Hatchways, Vents & Coamings, & General Equipment examined & found in order.

Examination of bottom a number of rivets in A & B Strakes (P+S) on flat bottom forward were found corroded, & were recommended to be renewed. The Owners however decided not to carry out any repairs, & the vessel was refloated and taken to Bowling Harbour, where she is now laid up for an indefinite period, as the Owners have not decided what they intend to do with her.

RY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

CONDITION OF THE

Good	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
"	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on Felt). When put on, Month Year
"	Bulkheads	Engine Room Skylights	Boats
"	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained From deck (State if wedges removed)
" in way of sidelights	Rudder	Scuppers	Sails
"	Steering gear and its connections	Cargo Hatchways	Equipment letter
"	Windlass	Hatches	Anchors, No. of
Good	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
inals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" length (on board) main diameter
ses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length
Bottom Plating		Transoms Pointers, & Crutches ditto	Hawser & Warps
		Timbers of Frame at openings ditto	Standing and Running Rigging
		Ditto Ditto at other places ditto	
		Stringers, Clamps & Sheifs ditto	
		Salting ditto	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,2,4," or "to remain as classed and to have record of survey, 1,2,4, and the notations of ss No. 1-24 and pTND24, &c."

This vessel, as now seen, is in efficient condition, & is eligible in my opinion to remain as now classed, without record of Survey, subject to corroded bottom rivets in A & B Strakes (P+S) forward being renewed & to the 3<sup>rd</sup> Special Survey N<sup>o</sup> 3 being held before end of December 1936.

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute

Character Assigned

GLASCOW

18 AUG 1936

Deferred

THURS. 31 DEC 1936

Surveyor to Lloyd's Register of Shipping.

Referred to

Lloyd's

Lloyd's Register Foundation

W465-0072