

7m,8,34.

23 OCT 1934

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "GEORGOS" Rpt. Sgt. No. 600

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.....

The class is subject to the shell plating in way of the drain plugs on port and starboard sides being examined at the next drydocking, and to 30 fathoms of chain cable being supplied to replace worn cable on board.

The Susak Surveyor now reports the ship placed on a pontonn and, on account of stranding and subsequent grounding, extensive damage found sustained to keel and bottom plating, floors, centre and side girders, tank top and margin plating, tank margin connections, etc.

The steering gear requires to be examined and the steering chains annealed.

The ship is at present laid up.

It is submitted action be deferred for repairs.



© 2020

Lloyd's Register
Foundation

Wh66-0120

Information of the committee