

2m.12.3

ceived by Chief Ship Surveyor 7-7-04

Received from Chief Ship Surveyor.....

ESSEL'S NAME Lot. L. S. Crane Report Hubb. No. 3904

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

ature of Survey

First entry

It is submitted that before this case receives the consideration of the Committee it should be pointed out to the Surveyor that there appears to be no reference whatever on his first entry report to there being a wood part awning deck, whereas in his letter of the 23rd June "the wood part awning deck" is mentioned. In view of this he should be requested to state definitely whether the iron plating deck of the part awning deck is wood sheathed.

It should at the same time be pointed out to him that the collective weight of the three bower anchors supplied to the vessel is incorrectly stated on his report.

Dr: to intro. 7/7/04

C. H. J.
7/7/04

© 2020

Lloyd's Register
Foundation

W466-0127

Quarter, 'tween Dks.,
in Hold

Angle on ditto.
Tie Plates . . .