

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "HELVETIER" ex "WAR TWEED". Report

Gls.

No 38778

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

Downton pump dispensed with for the present as approved in Standard Vessels. It is concluded the Owners are agreeable to fit same at the end of the War is requested to do so.

2. 100 A.1. (Steel)

1 Dk. (Steel).

Cell DB 198' 297t. FPT 84t. APT 60t.

FK. 4 BH. Cem. Lloyd's A. & C.P. B52', F23'.

5. 6. 19.

It is concluded the double bottom/in way of boilers, is watertight and has been tested as required, but the Surveyors should state if this is so.



© 2020

Lloyd's Register
Foundation

Wh66-0163

BEAMS. Poop Deck, Angle, Bulb Angle, Plate,

Tee Bulb, or Channel

Angles on upper edge

Spacing

Angle on ditto

Tie Plates

Deck, Material and thickness

Sheathing in Side houses

Steel

41 x

3 x 3 x

2 1/2

30 x