

APR. P.S(N) class. NOTED FOR POSTING

W473-0106

London Office 18 APR 1931

No. 3593

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 13/4 1931 When handed in at Local Office 15/4 1931 Port of Oslo

No. in Reg. Book. 81430 Survey held at Tonsberg Date, First Survey 16/1 Last Survey 8/4 1931

TONNAGE - GROSS 1767

Built at Rodby Havn By whom Rodby Havn Jernskibsværft When 1920

Owners A/S Pioner Owners' Address Oslo (if not already recorded in Appendix to Register Book).

Managers A.W. Nordstrøn & Kr. Gjølberg Port belonging to Oslo

XXXXXX in Dry Dock? Yes. Name of Dock Kaldnæs mek. Verk, Destined Voyage

DBorDBa feet; uE&B feet; f feet; f feet; f feet; MT feet tons; FPT tons; APT tons; MT feet tons.

Alterations in the existing records should be underlined. Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, the inner bottom plating, especially in the boiler space.

Report, No. 2106 Port Oslo

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned	Machinery and Boiler Surveys (including date of N.B. if any).
+100 A1		+ NE 5, 25
2, 30		+ LMC 9, 28
ssSea. No. 2-28		DBS2, 30
Carrying herring		1.5 (0.9)
in bulk.		P 9.28
		S.M. 9.28
		N.O.B.P. made 9.28.30
		Oil Eng

When held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs detailed in the body of the report, should be separated from Repairs due to other causes; when the Surveyor has not made a special damage report he is required to state whether he declines for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR Completion S.S.No.3 and Conversion.

This vessel placed in drydock and the bottom and rudder, stem and stern frame, shaft bracket examined. Bottom painted.

The chain cable ranged and the chain cable, chain locker and anchors examined. Generally examined decks, hatches, casing ventilators etc.

Plates in H strake stb. side found slightly indented, to be dealt with at owners' convenience.

The machinery for the herring factory has been removed.

Bridge front bulkhead moved from frames 77 to 69, the bridge deck for same length taken off. Flensing plan extended to frame 69 as per plan approved 28/1/1931, deckhouse moved accordingly.

REPAIRS -	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Repaired	✓	✓	✓	✓	✓	✓	✓	

State if Tanks have been examined inside	good	Dblg. Plates under Sounding Pipes	✓	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year	
State if Tanks now tested	see report	Engine Room Skylights	✓	Boats	
Bulkheads	✓	Coal Bunkers, Open'gs, Lids, &c	✓	Masts, Yards, &c.	good
Ceiling	✓	Scuppers	✓	Condition, how ascertained by exam. (State if wedges removed)	✓
Cement or Asphalt (State which.)	✓	Cargo Hatchways	good	Sails	✓
Rudder	good	Hatches	✓	Equipment letter	T
Steering gear and its connections	✓	Planking of Wood Vessels	✓	Anchors, No. of	3B. 15.14
Windlass	✓	Caulking	ditto	Cables (State if now ranged)	yes
Have Pumps now been examined and found efficient?	✓	Treenails	ditto	length	240' size 1 3/8'
Have Sluice Valves now been examined and found efficient?	✓	Breasthooks & Stemson	ditto	(on board)	240' size 1 3/8'
Have Watertight Doors now been examined and found efficient?	✓	Transoms, Pointers, & Crutches	ditto	Rule length	240' size 1 3/8'
Have Ventilators and their Coamings been examined and found efficient?	yes	Timbers of Frame at openings	ditto	Hawser & Warps	good
		Ditto ditto - at other places	ditto	Standing and Running Rigging	✓
		Stringers, Clamps & Shelves	ditto		
		Salting (State if examined.)	ditto		

Observations, Opinion as to Class, Recommendation, &c. :-

Whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the present survey, to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of main as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

The vessel is in good condition, in our opinion, eligible to remain as now classed in the Register Book with fresh record of survey 4, 31 and notation of S S Osl. No. 3-2, 30 " Carrying herring in bulk" subject to 4 plates in H strake stb. side be dealt with at owners' convenience.

Conversion fee	Kr. 120.-	Fees applied for, 13/4 1931
Travelling Expenses (if chargeable)	200.-	Received by me. 6.7.1931
Second Surveyor's Fee (if any)	245.-	

Committee's Minute TUE. 5 MAY 1931

TUE. 26 APR 1932

Character Assigned Referred for compl. L.M.C. (M) P.S(N) 4.31 Carrying herring in bulk Note 11.3 + 34. 1931

Surveyor to Lloyd's Register of Shipping



© 2019

Lloyd's Register Foundation

FRI. 28 APR 1931

