

Surveyor

Received from Chief Engineer Surveyor

Power

Rpt.

OS/0

No. 3593

of Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also early any exceptional features in connection with the case, so that the Classing Committee may have all the salient points endorsement. — Extract from Sub-Committee's Report, 24/5/92.

IAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No. 3.

7. 32 , partly held 5. 30

2. 31 now held

advanced and the following repairs effected (due to wear & tear)

Shaft renewed  
 main to port bed plate & cylinder flanging, Pistons - No  
 & Star No. 4, port thrust shaft coupling & Star  
 region have now been examined & found satisfactory

posed to complete the survey on vessels return from  
 grounds vessel autumn

mitted that this proposal merits approval and the vessel is  
 main as classed, and WILL BE eligible for the record  
 when the survey has been completed. & D.B.S. 1. 30

ring remains to be done to complete the Survey

umping Arrangements, fuel storage & daily  
 via tanks to be examined

at special restriction

31 New.

Ykur

© 2019



Lloyd's Register  
 Foundation

W473-0110