


10 spare carbon of letter
clean W.L.

M.V. "Joseph Medill"

This submitted the new castle
swimmers be informed that it is
noted from W. Akeson's First Entry
Report that 4 hatch beams were
fitted to each hatchway, although
the profile sketch of the vessel as
built shows only 3 to be fitted.
They should state which number
is correct and give the
scantlings as fitted.
They should also state what
cleats and tarpaulins were
provided as there is no
mention of these in their
report.

As the matter is urgent they
should reply by return.

W475-0085



Lloyd's Register
Foundation