

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME SIMON BOLIVAR Rpt. Ans. No. 15323

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Condition and alterations

The Amsterdam Surveyors report this vessel placed in dry dock, bottom cleaned and coated, port house pipes renewed (as per attaching approved plan) and minor repairs effected.

Small fractures at upper edge of sheerstrake at port of deckhouse have been repaired by electric welding and the Surveyors recommend the repair be specially examined at the next dry docking. alterations have been effected to the Promenade Deck and deckhouse in front of it in accordance with the attached plan.

It is submitted the vessel appears worthy to remain as the attached subject as recommended, approved plan.

classed with record of survey 738 as recommended.

100 AT
with freeboard
738 Ans.
Fitted for O. F. etc

} subject etc



© 2019
22.7.38.

Lloyd's Register
Foundation

W478 0086