

S.S. "ATTIKOS"

EXTRACT FROM ROTTERDAM REPORT NO.23070 DATED 1.8.34.

In order to make vessel in accordance with the Convention freeboard requirements the following repairs have been carried out:-

In bridge space bunker 3 coal hatchways have been renewed by $\angle 9 \times 3\frac{1}{2} \times .50$ with restangle bars, cleats, hatches on freeboard deck in bridge space round 4 flush holes (trimming holes) coamings of $\angle 9 \times 3\frac{1}{2} \times .50$ with complete battening down arrangements have been fitted. On port side one length of bulwark profile renewed.

hoked

7. 8. 34.

*See assignment Cr.
dated 2.8.34*



© 2019

Lloyd's Register
Foundation

W 478 - 0146