

124 MAR 1936

Received from Chief Ship Surveyor

Ship Surveyor

"NORDLAND"

Rpt.

P.N1.

No. 2542

ME

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Port Natal Surveyor reports this vessel examined afloat and on account of damage sustained during heavy weather some repairs have been effected to deck fittings.

The Surveyor recommends the vessel be placed in dry dock for repairs to No.5 feed water tank port side and examination of rudder etc. at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey subject as recommended.

As now, subject etc.



2019  
23.3.36

Lloyd's Register  
P.T.O.  
Foundation

W482-000012



"NORDLAND"

-2-

The Surveyor should be requested in future similar cases to state definitely in his report whether repairs, and if so, what repairs have been carried out. His recommendations in respect to No.5 feed water tank and the rudder and pintles should also appear in the space for the recommendations at the foot of the reports and of the Interim Certificates.



© 2019

Lloyd's Register  
Foundation

W482 -0007-1