

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 22 APR 1930)

Date of writing Report 1 April 1930 When handed in at Local Office 1 April 1930 Port of Jacksonville, Fla.
 No. in Reg. Book 28896 Survey held at Jacksonville, Fla. Date, First Survey 13th Dec. Last Survey 1920
 on the Machinery of the Wood, Iron or Steel S.S. "ELSA MENZELL" ex Inchdairnie
 Tonnage Gross 6596 Net 4074 Vessel built at Kinghorn By whom Kinghorn S. B. Co. When 1981-5
 Engines made at Glasgow By whom J. Harden & Co. Ltd. When 1921
 Boilers, when made (Main) 1921 Owners' Address (Donkey)
 Owners Menzell & Co. Reederei Owners' Address (if not already recorded in Appendix to Register Book)
 Managers Port Hamburg Voyage Jaf to Hamburg
 If Surveyed Afloat or in Dry Dock Afloat (State name of Dock.)
 Donkey Boilers Pressure—200 Main Boilers
 Key Boilers

Report No. Port

Particulars of Examination and Repairs (if any)

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on damage (the cause of which must be stated) should be separated from repairs due to other causes; and initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose, and why they were declined?

Damage report made by anyone else? If so, by whom? Underwriter's Surveyor

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

" Donkey "

not done, state for what reasons? Survey for installation of new turbines

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Shaft now been changed? no If so, state reasons

Shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done?

Done:- New turbines installed, tried out under steam at dock & sea trial & found satisfactory.

Turbines shipped from Glasgow by J. Harden & Co. Ltd.

marks:- MT 81
L.P. BELT 110 lbs.
PER 10"

TESTED 10 30 lbs.

H.P. P. M. G.
7. 7. 19.

L.P. 26. 2. 20.
P. M. G.

B. The astern buckets of L.P. turbine (referred to on previous report) are now in order.

General Observations, Opinion, and Recommendation:—The machinery of this vessel

is clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9, 11, E.C.M.S. 9, 11, or L.M.C. 9, 11, 12, 13, F.D., &c.)

now seen, is in good condition, eligible, in my opinion, to remain classed & to have record of L.M.C. with date

Fee (per Section 25) £

Damage or Repair Fee (if any) (per Section 25.) £

Expenses (if chargeable) £

Fees applied for

19

Received by me,

19

Committee's Minute

NEW YORK APR 9 - 1930

signed + L.M.C. 2.30

Condition Satisfactory

FRI. 4 JUL 1930

TUE. 8 JUL 1930

Shugh Boyle 2019
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation
W482-0095

Supplementary Rpt.

It is submitted that
this vessel is eligible to
remain as CLASSED. *without*
8pl *Condition.*

N.B.—If this Report is copied

pread the ink, or to cause it to show through to the other side.

26/4/30

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2019

Lloyd's Register
Foundation