

7m.8.34.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

-8 NOV 1935

VESSEL'S NAME "NORDLAND" Rpt. Shi. No. 3946

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey .....

The Shanghai Surveyors report this vessel examined afloat after collision with lighters and <sup>SHELL</sup> plating etc. on port side in way of No.2 hold found to be indented.

No.5 (<sup>FRESH</sup> food water) tank port side was reported to be contaminated with salt, soundings were taken but no leakage found.

The Surveyors recommend the vessel be specially examined for indented plating at the next dry docking and No.5 (<sup>FRESH</sup> food water) tank port side be not used for boiler feed water until repaired and retested.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.



© 2019  
Lloyd's Register  
Foundation

W482 -0256

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is not their duty to ensure that the vessel is seaworthy at the time of survey."

signed) a  
now verified  
✓  
just  
dur  
voya  
5  
of  
rec  
ing  
Sov  
mat  
Y.M. of Wo  
if on Felt).  
out on, Mont  
ds, &c. ....  
now ascertain  
if needges  
letter .....  
o. of .....  
te if now r  
h.....  
on board)  
length.....  
Warps .....  
ad Running  
register Bo  
classed and  
opin  
at