

W482-0341

JACKSONVILLE, FLA.

13th July 1929.

HUGH BOYLE

J. Fletcher, Esq., Owner, survey the Steel Screw Steamer "INCHDAIRNIE" of Glasgow, 6596 tons gross register, for the purpose of ascertaining the nature and extent of the damage stated to have been caused by supplementary feed valve being left open and causing boilers to salt.

For further particulars see Log Book and Protest.


On examination of the vessel while lying afloat at Savannah, Ga., on the 10th July 1929 found all boilers in bad condition.

RECOMMENDED:- That all boilers be retubed. That brick work be overhauled and put in good condition. That all mountings be overhauled and stud and nuts renewed where necessary. That all iron piping (feed line) be renewed. That turbines be opened for examination.

The above recommendations were made with the view of placing the vessel in the same good condition as before the boilers were salted.

FEE & EXPENSES. \$ 64.72

*Hugh Boyle*



Lloyd's Register  
Foundation



in D  
 Last  
 Pan  
 (Period  
 cause  
 acco  
 beside  
 dates  
 In dan  
 offe  
 Was a  
 Did the  
 Do  
 If this w  
 And wh  
 Also wh  
 Survey  
 Did the s  
 Did the  
 Did the s  
 Did the s  
 Did the s  
 Has scre  
 Has shaft  
 Has the  
 State the  
 If the Sur  
 To be  
 Gener  
 (State  
 vesse  
 way Fee  
 cial Dan  
 (1  
 travelling  
 Comm  
 Assign

1901 JULY 1901

WILLIAMS

1. The vessel, "The Glasgow", 6800 tons gross register, for the purpose of ascertaining the nature and extent of the damage stated to have been caused by supplementary feed valve being left open and causing boilers to split.

For further particulars see Log Book and Protent.

On the 10th July 1901 the vessel while lying at anchor at Bevenham, Ge., on the 10th July 1901 found all boilers in bad condition.

RECOMMENDATIONS:- That all boilers be repaired. That brick work be overhauled and put in good condition. That all mountings be overhauled and where necessary, that all iron piping (feed line) be renewed. That turbines be opened for examination.

The above recommendations were made with the view of placing the vessel in the same good condition as before the boilers were split.

*W. J. P. 1901*

THE & EXPENSES. £ 64.75

*W. J. P. 1901*  
*W. J. P. 1901*  
*W. J. P. 1901*  
*W. J. P. 1901*

*W. J. P. 1901*



© 2019

Lloyd's Register  
 Foundation