

s.s. "INCHDAIRNIE"

Ply. 6686.

Brickwork in boiler furnaces repaired, a few tubes renewed in port and starboard boilers, feed valves overhauled, 2 safety valve springs renewed, feed, lubricating oil and air pumps overhauled and minor repairs effected.

IF IS SUBMITTED the vessel will be eligible for the record * LMC 2.29 when the suction valve chest of the main feed pump has been renewed, and the class be continued subject to this being done on return from the present voyage and to the safety valves of the centre boiler being adjusted under steam at the first opportunity.

27
27. 3. 29.



© 2019

Lloyd's Register
Foundation

W480-0346