

Urgent - Cable Requested

s.s. "INCHDAIRNIE"

- Falmouth Report No. 6594


This vessel has recently been under repair at Falmouth where a new HP turbine and casing was fitted. The old HP turbine was put ashore with a view to being repaired. The Falmouth Surveyors recommended that if it is intended to use this turbine again the rotor shaft and one thrust cap should be renewed and the bearings remetalled.

Mr.J.Fletcher, the owner, called at this Office today and stated that trouble had been experienced with the thrust of the new turbine and the vessel was returning to Falmouth.

Mr.Fletcher further stated that in the circumstances he proposed, if necessary, to effect minor repairs to the old turbine and to refit it in the vessel without however renewing the rotor shaft, as recommended by the Falmouth Surveyors; he enquired whether his proposal could be accepted and was informed that before consideration could be given to the matter it would be necessary to receive a further report from the Falmouth Surveyors who would be advised and asked to give the case prompt attention.

IT IS SUBMITTED the Falmouth Surveyors be advised by wire and requested to give the case immediate attention.

14#
Jul 16. 11. 26



© 2019

16.11.26.

Lloyd's Register
Foundation

W48L 0432