


s.s. "LIGONIER"

Lon. 103203.

The Surveyor reports that the electrical installation is in unsatisfactory condition and the wiring and fittings in the pump room are dangerous and unsuitable for a vessel carrying petroleum in bulk.

The fastenings of the sea connection gratings require to be put in order.

It is submitted action be deferred subject to the necessary repairs being effected before the vessel goes to sea, the electrical installation not to be used until it has been repaired and satisfactorily reported upon by the Society's Surveyors.



23.7.36.



© 2020

Lloyd's Register
Foundation

W487 0105