

subject to shell plate G 3 from aft, starboard side, E.W. 2.36 & 12.37  
being specially examined at the next dry docking.  
The 1<sup>st</sup> S.S. No 2, due 10.38, has been partly held.

1

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor 23 AUG 1938

VESSEL'S NAME KOLL

Rpt. H. J. E.

No. 2905

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.)

Area of Survey

DAMAGE.

Damage through grounding etc.

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed .....	1						
Removed and faired or repaired.....							
Faired or repaired in place.....	1			3			

Other items:- Repairs effected to shell riveting & large beads.  
Vessel examined in dry dock, bottom cleaned & coated.  
E.W. repairs as above examined & found satisfactory

It is submitted the vessel is worthy to remain as classed with

Record of Survey 7.38 subject as above.

100A-1.

7.38 H. J. E.

Carrying Pet. on bulk. subject



© 2020

Lloyd's Register Foundation

W49-0053

at next docking.

