

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"FARNHAM"

Rpt. *Npt*

No. *23969*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/32.)

Result of Survey

DAMAGE.

Damage through striking dock wall during air raid.

How repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....	<i>1.</i>						

Other items:- *Vessel placed in drydock, repairs effected to fore-castle gunwale bar, some rivets renewed & minor repairs carried out.*

Bottom Coaled

It is submitted the vessel is worthy to remain as classed with record of Survey *5.38.*

*100A1
5.38 Npt.*

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



© 2019

Lloyd's Register Foundation

w497-0123

to write on or below

RETAIN

[Faint, illegible handwritten text, possibly bleed-through from the reverse side of the page]



© 2019
Lloyd's Register
Foundation

Transfer in on or below
Survey
Gen
Inner E
Strings
Keelson
Floors
Transvs
Lough
Revers
Frames
Tran
Breast
Decks
Gan
Co
Beams
Outside
"
BREAST
DECK
GANKIN
COAMIN
BEAMS
OUTSIDE
"
SUMM
No.
No.
No.
No.
REP
In d
of th
La
W tot