

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

19 OCT 1936

L'S NAME

Australia

Rpt.

Acker

No. 601.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

of Survey **REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH stoppage**  
 of circulating pump.

New impeller shaft fitted to circulating pump. Also 17 eccentric shaft removed.

It is submitted that  
 this vessel is eligible to  
 remain as **CLASSED**.



© 2019

17/10/36.

Lloyd's Register  
 W497-0186  
 Foundation