

24 MAR 1937

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "AEGEUS" Rpt. B.As. No. 14898

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

The class is subject to indented plating being repaired at the first opportunity.


The Buenos Aires Surveyors report the ship examined afloat after grounding.

Soundings taken and no signs of leakage or damage found.

The Surveyors, however, recommend the vessel be examined in dry dock at the earliest opportunity.

It is submitted action be deferred and the Owners informed of the Surveyors' recommendation.

Insert in S.R.L. 'Dry docking (grounding)'



© 2021

Lloyd's Register
Foundation

W499-0379