

WS-0058

924

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME *Steel Se Se AUDITOR* Report *Els* No. *43766*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

Time of Survey *1st Entry* When due

✦ 100A.1. (Steel)

2 Sko (Stl)

Cell D.B. 35i 1118t, D.T.a 3i 850t, F.P.T. 52t, A.P.T. 22t.

F.K, 8BH (1BH to 2nd Dk), Cm, Lloyds A & CP.

P 37', B 138', F 52'.

Ltr. 28/6/24

See letter 27.6.24

It is concluded that, as no mention is made in the report regarding the deck plating & beams for the 3rd Deck in No 1 Hold, this deck has not been fitted.

Loop Deck, Angle, Butt Angle, Plate,	8x3x3/4x38	8x3x3/4x38	Bridge Deck Stringer Plate, br'dth & thickness	65x
Toe Bolt, or Channel			Angle on ditto	5x5
Angles on upper edge				