

2 E

Received from Chief Engineer Surveyor

Chief Engineer Surveyor

NAME

Bury Hill

Rpt.

Ans. 29 JUL 1936 3756

No.

Reports of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S.~~ No.

Survey

This Survey, due 9.36 ~~partly~~ now held

now

completed, and the following repairs carried out (due to wear & tear):-

Examination found cracked at end of liner - Now removed
 Surveyor states the donkey boiler will not be used again
 they should be requested to state the reasons for the discontinuance of
 use of this boiler.

It is submitted the vessel is eligible to remain as classed, with

ation of

130. 7. 36

S.N. 7.36

Subject to the as recommended.
 DONKEY BOILER
 not being used again.

© 2020

Lloyd's Register
 29.7.36
 Foundation

DB

name

WS05-0070