

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

S NAME Kernwood Rpt. Lon. No. 109662

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey DAMAGE.

age through Enemy Action

repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
ewed .....							
oved and faired)							
r repaired.....)							
ed or repaired)							
n place.....)							

er items:- Vessel placed in dry dock & bottom Coated

Minor repairs effected

abricated Steel N.T Box fitted on shell to take main injection.

s submitted the vessel is worthy to remain as classed with 5,41

ord of Survey as recommended

100A1

5,41 Lon.

