

SS. "Macedonier"

1st Entry Report. & damage due to propeller
striking wall & to HP piston valve seizing

It is submitted that
this vessel is eligible for

THE RECORD. + LMC. A. 21. F.D. C.L.

Recd

18/4/21



GRG

Lloyd's Register
Foundation

51-0236

ds to lamps carrying _____ Amperes, comprised of

go light cables carrying 15 Amperes, comprised of

4 wires, each

.036

S.W.G. diameter,

.0070

square inch