

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.

LONDON.
REGD NO. 17 (SGD) 1919

TUE 16 DEC 1919

NSD

Port Sydney, N.S.W.

COPY AS ABOVE

27th October 1919.

This is to Certify that I have

Wm. ROBERTSON. (SGD)

Surveyed the Boiler and Machinery of the T.S.S. "ADOLPH WOERMANN" at the request of the Master, examined the Starboard and Centre Furnaces of the Port Aft Boiler, and the Centre Furnace of the Centre Aft Boiler and the Starboard Furnace of the Port Forward Boiler.

Found the S. & C. Furnaces of the Port Aft Boiler deflected on Crown at one side, each, middle of length, difference of diameter $3\frac{1}{8}$.

The Centre Furnace of Centre Boiler and the Starboard Furnace of Starboard Boiler deflected $1\frac{1}{4}$ ". (see other side.)

and that I have transmitted to the Committee of Lloyd's Register

of Shipping, London, a Report, as on the other side, stating

that all repairs recommended by me have been completed to

my satisfaction.

(SGD) Wm. Robertson.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of omission, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Examined the furnaces of all Boilers and found the Damage as mentioned, also the insides of the damaged Boilers,

No trace of grease or oil was found, the Boilers now clean internally and the deflected furnaces set up and now seen practically a circle.

(SGD)

W.M. ROBERTSON

W.B. N.W.

1/2

COPIED AS ABOVE.

S.A.P. October 1919.

Examined the furnaces of all Boilers and found the Damage as before mentioned, also the insides of the damaged boilers, no trace of grease or oil was found, the boilers now clean internally and the deflected furnaces set up and now seen practically a true circle.

(SGD) Wm. ROBERTSON.

Examined the furnaces of all Boilers and found the Damage as before mentioned, also the insides of the damaged boilers, no trace of grease or oil was found, the boilers now clean internally and the deflected furnaces set up and now seen practically a true circle.

At the Port of Cardiff May 1st 1919
Wm. ROBERTSON
Engineer to the Commissioners of the Port of Cardiff

At the Port of Cardiff May 1st 1919
Wm. ROBERTSON
Engineer to the Commissioners of the Port of Cardiff

At the Port of Cardiff May 1st 1919
Wm. ROBERTSON
Engineer to the Commissioners of the Port of Cardiff

At the Port of Cardiff May 1st 1919
Wm. ROBERTSON
Engineer to the Commissioners of the Port of Cardiff

At the Port of Cardiff May 1st 1919
Wm. ROBERTSON
Engineer to the Commissioners of the Port of Cardiff

Referred to the Chief Engineer Surveyor.

Mr. S. J. Hill to note
Also refer Mr. S. J. Hill to note
Also refer Mr. S. J. Hill to note

(SGD)

With suggestion.

© 2020

Engineering
Foundation