

Subject to shell plates C.3 (p.s.) wasted at after butto being  
dealt with at next dry docking.

11

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME

THORPE HALL

Rpt. *Hul* No. 48451

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Survey

The *Hull* Surveyors report this vessel placed in  
dry dock, bottom cleaned and ~~coated~~ <sup>examined</sup>, repairs to *butts of shell plates C.3*  
*as above,* (p.s.),  
and ~~minor repairs~~ effected.

It is submitted the vessel appears worthy to remain as  
classified with record of survey 11.37 *Without special condition* as recommended.

100 A.1  
Shelter Ok. with fbd. } *Without etc.*  
11.37 *Hul*



© 2020

*all wh.*  
Lloyd's Register  
Foundation  
16.11.37

WS10-0179



RETAIN



© 2020

Lloyd's Register  
Foundation