

Subject to shell plate C₁ (ps) & D 6.37 being
specially examined at next drydocking

11

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Pegaway

Rpt.

hwc

No. 96057

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Newcastle Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs to and minor repairs effected.

The E.W. repairs as above examined & found efficient.


It is submitted the vessel appears worthy to remain as classed with record of survey 3.38 ^{subject as above} as recommended.

100 A/

3.38 Shl

} subject re.

The Certificate of Classification is endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book



31. 3. 38 2020

Lloyd's Register
Foundation