

COPY.

# Lloyd's Register of Shipping.



Port

OF LIVERPOOL

9th March, 1936.

This is to Certify that

E. H. DEAN

the undersigned Surveyor to this Society did at the request of the Owners representative, survey the T.S.S. "EL PARAGUAYO", 8508 gross tons of Liverpool, whilst lying in the Langton drydock on the 11th February, 1936 and subsequently whilst lying afloat in the Canada dock, for the purpose of ascertaining the nature and extent of damage stated to have been caused:-

- 1) By grounding off Martin Garcia Island, voyage from Santos to Monte Video, January 2nd, 1936.
  - 2) By heavy weather various dates, January and February 1936.
- For further particulars see log books.

Attended as requested and:-

FOUND

- 1) Bottom and rudder scrubbed and bare of paint.

Small fracture at after corner of main injection on starboard side.

- 2) Handrails on port side of vessel abreast No. 2 hatch, damaged.

Handrail on starboard side of vessel abreast No. 3 hatch damaged.

RECOMMENDED

To be cleaned, scaled as required and re-coated. Rudder pintles to be examined and cement on nuts renewed.

Fracture to be electrically welded up.

To be overhauled as required.

To be part renewed.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or for any error of judgment, default or negligence in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



COPY.

FOUND

Firemans' deck leading

Small fractures in sheer  
strake, port and starboard  
sides at forward corner of  
bridgehouse.

RECOMMENDED.

to be overhauled.

To be electrically welded up.

The above recommendations were made in order to  
place the vessel in the same condition as before the damage  
occurred, and have been carried out in a satisfactory manner.

*E. H. Deane*

SURVEYOR TO LLOYD'S REGISTER.

Fee: £3:3:0:

RECEIVED



© 2020

Lloyd's Register  
Foundation

WS14-0144 2/2



the

the

8800

on

in

and

(1)

(2)

(3)

(4)

(5)

(6)

(7)

(8)

(9)

(10)

(11)

(12)

(13)

(14)

(15)

(16)

(17)

(18)

(19)

(20)



Y903

Belmont, N.Y.

On March 11, 1964

Dear Mr. Belmont:

I am writing you to advise you that I have received your letter of March 10, 1964.

I am sorry that I cannot give you a more definite answer at this time.

I am sure that you will understand my position.

Sincerely,  
J. Edgar Hoover

*Handwritten signature*

Very truly yours,  
J. Edgar Hoover

OFFICE: 100

RETAIN

5/5  
4410-412M



© 2020  
Lloyd's Register  
Foundation