

250,130.

Spl. notice take 16/9/13

F.E.

Received by Chief Ship Surveyor *27.6.12*

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Twin S/S 'El Paraguayo'* Rpt. *Hpl* No. *14439*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *88.75*

Depth "d" *11.41*

Framing: Table No. *3 page 13*

Description *Built angle as approved*

Longitudinal No. *39050*

Proportions Length = *9.5*
Depth =

Bridge Deck Sheerstrake *as per Rule*

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **100A.1 (Steel) Shellin DK* with freeboard," as recommended. The Summer freeboard of *9' 2"* from centre of disc to top of statutory deck line at *Shellin* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

W574-0199


** 100A.1. (Steel) Shellin DK with freeboard.*

3 Dks (Stl) + Shellin DK (Steel)

WB = Cell 2B a 113 u 24B 81 f 189' 10996. F.P.T. 636-APT 766

FK. 7BK. Cam' Lugs a x CP. B 135' + F 37' on Shellin DK.

Date of Build 4.12.



Lloyd's Register Foundation

PILLARS, IN

" " Q

WEB FRAME