

2 JUL 1930

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor, 2 JUL

VESSEL'S NAME Steel Sc. Sr. "CLAN MACKENZIE". Rpt. Bmn. No. 1275

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

The 1st S.S. No.3, due 6.29, has been partly held.

The forefoot plates required to be dealt with at the next dry docking and indented side plates and port bow plating dealt with at the Owners' convenience.

The Bremen Surveyors now report the vessel placed in dry dock, bottom coated and the 1st S.S. No.3 completed.

The forefoot plates have been renewed, some indented plating and beams faired and minor repairs effected.

An exhaust turbine has been fitted and the tank top in way reinforced.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.30 and notation of S.S. No.3-12.29.

100 A. I.  
Shelter dk with fbd.  
6.30 Bmn  
S.S. No. 3-12.29

W. A. M. A.  
1.7.30

Delete "Forefoot plates, indented side and bow plating and repairs" from S.R.L.

The Certificate of Classification to be endorsed "~~Cargo battens not fitted~~ and the same notation to be printed in the Register Book.



© 2019

Lloyd's Register  
Foundation

Rpt  
4/6