

Subject to indented shell plating etc on port side forward being permanently repaired at the Owners convenience.

11

4 MAR 1937

by Chief Ship Surveyor

Received from Chief Ship Surveyor

'S NAME

Shk "KAKARIKI"

Rpt.

*Syd*No. *15362*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/32.)

f Survey

The

Sydney

Surveyors report this vessel placed in

dock, bottom cleaned and coated, ~~repairs to~~~~minor repairs effected.~~

The indented plating as above examined & found efficient.

It is submitted the vessel appears worthy to remain as
 ssed with record of survey *1.37* ^{*subject as above*} as recommended.

*100 A1**1.37 Syd } Subject etc**WAB**[Signature]**1.3.37*

© 2019

Lloyd's Register
Foundation

WS19-0140

RETAIN



© 2019

Lloyd's Register
Foundation

GROSS ... 65
UNDER DK. ... 41
NET ... 41
Surveyed After
B=CellDB
al capacit
N.B.—All atten
If the Vessel
he tanks exami
ers, and of the
ast Repo
ological Surveys,
ause of Repairs,
n account of Da
and besides being
eplacement of A
he back of this f
amage cases w
ffered his serv
PAIRS, OR E
The v
in g
ref
at the
Dicks
and
ARY OF DAMAG
Renewed ...
Removed and Fair
Faired or Repaired
NT CONDITION
ag of Decks ...
igs
& Fastenings
Plating
hooks
ms
e Frames
edinals