

2m.11.38.

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

LAMMOT DU PONT

Report

N. Yk.

No. 42072

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(3RD No. 1 SURVEY PARTLY HELD.) CONDITION.

When due 8.42 When proposed to be completed

Portion of Survey held, &c. Examination of anchors, cables and chain locker.

Subject to shell plate F.3 (s.s.) found fractured
and ~~was~~ temporarily repaired, being renewed at the
next dry docking.

was
5.5.42

S.S. PART HELD.



© 2021

Lloyd's Register
Foundation

WS2 - 0020

length
(on board)
Rule length