

Chief Surveyors 15. 10. 36

Received from Chief Surveyors

SHIP'S NAME

M. S. "SAN LEON"

Report

Liv.

No. 107820

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Condition (afloat)


When due

Subject to shell plates Nos 7, 8 & 9 in 1st strake below sheer on port side, repaired by E.W. 3rd being specially examined at next dry docking.

repairs to do
MAB

The vessel has been delivered at Rooyt to be broken up.

The Surveyors should be requested to state when the three



Lloyd's Register
W520-0094
Foundation

71, Fenchurch Street

RETAIN



© 2020

Lloyd's Register
Foundation

REPAIRS /

Call
a v

Four
long
Boop
vul
pla
Flap

SUMMARY OF

Renewed

Removed

Faired on

PRESENT CON

Decks

hauling of De

Coamings

Beams & Fast

Outside Plating

" " in

breasthooks.....

ransoms.....

frames

teverse Frame

ongitudinals.

Transverses.....

Floors

Keelsons

Stringers.....

Inner Bottom

Gener