

Rpt No 15760

Port of **GRIMSBY**

Feb 14/28

19

REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined
Spars, and Rigging, and Iron Work of same, of the
Ss Earl. Durham

report that I found *The fore Rigging & fore Stay*
condition, all 4 Wounds & Stay renew
Steps on Mast Ladder Resizing on
Derrick Guys renew, New Lantern Stays
and Stays,
Spars & Ironwork Satisfactory

J. Hasto Foreman Rigger

10 6

yors,

Register of British & Foreign Shipping,

GRIMSBY.



© 2020

Lloyd's Register
Foundation

W526 0198

forwarded to the Chief Ship Surveyor.

RETAIN



© 2020
Lloyd's Register
Foundation

VERMINE

Division of Building & Lumber Shipping

3 01

Angles on upper e

Deck

the Deck

upper e

ck, Angl

ly, or Cl

upper e

k, Angl

th, or Cl

upper e

Fourth

le Plate,

Beck, S

Plate, T

Long B

reck, S

Plate, T

Rema

in Eng

ness of

PLATE

Outside

internd

Angles

depth

and th

Angle

to

to

Angles

in Dlb

Solid

nged

Double

ed at

half

ends

fine

and

ginder

thick

ne for

the

the

the

length

on cent

"

the Bot