

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 14-3-1928 When handed in at Local Office 14-3-1928 Port of Grimsby

No. in Survey held at Grimsby Date, First Survey 20-12-27 Last Survey 12-3-1928
eg. Book.

536 on the Wood, Iron or Steel Se "TOTNES" (ex "EARL OF DURHAM")

TONNAGE: Built at Slidrecht By whom Schepers Baanboks v/h When 1918

GROSS 320 Owners J. C. Wilton & Co. Ltd. Owners' Address T. Udenlof

UNDER DK. 210 Managers Port belonging to London

NET 138 on Slipping, Boat Name of Dock Charlton's Destined Voyage Goolse

Surveyed Afloat or in Dry Dock?

WB=Cell DBor DBa feet; uE&B feet; f feet
Total capacity tons; FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs due to account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

Repairs, or Examination as per Rule, for Special Survey No 3 and Classification

done:-

Vessel placed on slipway bottom and middle cleaned, examined, coated

the hold, peaks, chain locker, bunkers and E & B and accommodation

paces cleared and examined; ceiling removed as required by the Rules

the plating, framing and all ironwork sealed and coated throughout.

the plating in way of the sidelite examined.

the after peak tank water tested according to Rule

Anchors and cables, mast, wedges, rigging, general equipment

decks, hatchways, hatch covers and supports, tarpaulins, chutes and

bathtubs, ventilator coamings and covers, E & B bearings and deckhouse

SUMMARY OF DAMAGE REPAIRS:—

Renewed ...

Removed and Paired or Repaired ...

Paired or Repaired in place ...

PRESENT CONDITION OF THE

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt (State which)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting (state if examined) ditto

Gerters, or Y.M. of Wood Vessels (State if on Felt) When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length 180 ft size 1"

Rule length 180 ft size 1"

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is in a good and efficient condition and eligible

in our opinion to be classed 100A1 in the Register Book and

to have record of survey 3.28 and notation of

ss No 3-3.28.

Survey Fee (per Section 20) £ 12 : 0 : 0

Special Damage or Repair Fee (if any) £ 5 : 0 : 0

Travelling Expenses (if chargeable) £ 3 : 0 : 0

Second Surveyor's Fee (if any) £ : :

Committee's Minute

Character Assigned

TUES. 3 APR 1928

100A1

ss No. 3. 3.28 + A.B. 3.28

S.N. 3.28 + L.M. 3.28 + A.E. 5.00, refilled 28.

Fees applied for, 15.3.1928

Received by me, J. R. Palmer & W. H. Kinlay

Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register

W526-0202/2A

3. If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Wear & Tear repairs:

Alterations

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES

The following repairs on account of damage
sustained due to grounding in the river Thames on the
8th January, 1926, have been carried out.
Counting from fore end:

Nov 30th Bell plates removed.

ps: A Nos 2-3-4-5+6 and 13 Nos 4-5+6 removed, faired and replaced
 ss: A Nos 3-4-5+6 " 13 Nos 4-5+6 " " " "
 in way; twenty four floors removed, faired and replaced
 Five centre keelson intercostal plates removed and inserted

pt. 9a.

Continuation of Report No. 15760 dated 14-3-28 on the

SS "TOTNES" (ex "EARL OF DURHAM")

Costs of damage repairs:

fained in place. forty eight side keelson intercostal
plates fained in place. eight hold strappings and
one ladder removed, fained and replaced.
Fore peak suction pipes removed. All hold ciling
and part cargo battens removed.
Silge Beels: bulk plate removed p 75.

See also F. G. Report.

A. R. Palmer

Wm^c Kenney