

N. 144,537

t. 8.

(Received at London Office MON. AUG. 9 1920

No. 2911

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7 Aug 20 When handed in at Local Office 20 Port of Miyor
No. in Survey held at Miyor Date, First Survey 1st June Last Survey July 16 1920
Reg. Book. 24152 on the Wood, Iron ST Cheriton of Thomas Robins Master W H Francham
TONNAGE:— Built at Middlebury By whom Smith Dock Co L When 1917
GROSS 275 Owners W Pettit L Port belonging to Muyor
UNDER DE. 169 Owners' Address Records
NET 107.43 (if not already recorded in Appendix to Register Book).

Surveyed Afloat in Dock Slipway Name of Dock Muyor Dock Destined Voyage Fishing

WB=CellDBorDBa feet; uE&B feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ☒ for Special Survey. Date of last Survey and of Periodical Surveys. Years assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Classification

Vessel placed on slipway bottom Keel, and rudder cleaned, examined, and recased Examination made of keel, stowage, fishroom, beams, and machinery spaces, the ceiling lifted when fitted in vessel by machinery space, and vessel examined in way of same Solid Cement fitted over floor in other parts Hamam made mast, rigging, Decks Hatch coaming hatches steering gear machinery casings, and equipment. The fishroom was renewed, and all iron work scales, and recased throughout, all defects were made good, and vessel fitted out for fishing

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE	Stringers	Good	Dblg. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels (State if on Feet.)			
Decks	Inner Bottom Plating		Engine Room Skylights	"	When put on, Month Year			
Caulking of Decks	State if Tanks have been examined inside		Coal Bunkers, Open'gs, Lids, &c.	"	Boats	Good		
Waterways	State if Tanks now tested		Scuppers	"	Masts, Tars, &c.	"		
Coamings	Bulkheads	"	Cargo Hatchways	"	Condition, how ascertained Examination			
Beams & Fastenings	Ceiling	"	Hatches	"	(State if wedges removed)			
Outside Plating	Cement or other (State which.)	"	Planking of Wood Vessels	"	Sails	Good		
Caulking of ditto	Rudder	"	Caulking	ditto	Equipment letter			
Rivets	Steering gear and its connections	"	Treenails	ditto	Anchors, No. of	2 B 1 S		
Breasthooks & Crutches	Windlass	"	Breasthooks & Stemson	ditto	Cables (State if now ranged)	Yes		
Transoms	Have Pumps now been examined and found efficient?	Yes	Transoms, Pointers, & Crutches ditto		" length 105 size 1 1/2			
Frames	Have Sluice Valves now been examined and found efficient?	Yes	Timbers of Frame at openings ditto		" Rule length 105 size 1 1/2			
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Yes	Ditto ditto at other places ditto		Hawser & Warps	Supers		
Floors			Stringers, Clamps & Shells ditto		Standing & Running Rigging	Good		
Keelsons			Sitting (State if examined.)					

General Observations, Opinion as to Class, Recommendation, &c.:—This vessel

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

is in a good, and efficient condition, and in my opinion warrants the favourable consideration to be classed 100 A1 Str trailer and have notation of SS No 1-20 entered in the register book

Survey Fee (per Section 28) £
Damage or Repair Fee (if any) per Sec. 28) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for, £19
Received by me, £19

J H Johnson

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI. SEP. 3 1920

See minute on F.E. report.



© 2019

Lloyd's Register

W531-0077

Total No. of Visits