

Surveyed the *Special Screw Steamer "ARMURU"*, 2765 tons gross,  
No. 20206 in the Register Book, while lying in dry dock

10,36.

Inspected by Chief Ship Surveyor .....

Received from Chief Ship Surveyor ..... 7 NOV 1936

SHIP'S NAME "ARMURU" Rpt. Msl. No. 9108

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Remarks of Survey .....

The Marseilles Surveyors report the ship placed in dry dock, bottom cleaned and coated.

The Surveyors recommend shell plate B2 on the port bow found scrubbed and wasted be dealt with at the next dry docking.

It is submitted the vessel appears worthy to remain as classed with record of survey 10,36 subject as recommended.

100A1 ) Subject etc.  
10,36 Msl. )

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



2019  
6.11.36

Lloyd's Register  
Foundation  
W533-0006

10m. 11.34 T.

Ship  
676  
No. 20206  
of Wood V  
Felt).  
Month.....  
scertained.  
edges ren  
r all.  
nose ran  
oard  
th  
ps  
unning Rig  
ter Book  
ed and to  
ine  
cup  
the