

Undertaking Casent to Chief Surveyors 29.3.33Received from Chief Surveyors 31 MAR 1933VESSEL'S NAME Steel S.S. Luvuvavou Report air. No. 97991**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ature of Survey S.S. No. 2 When due 3.31

BS due 12.31? General Examination(Vessel still laid up)

The class is subject to the stern frame, repaired by electric welding 12,26, being specially examined at the next dry docking.

The 1st S.S. No.2 became due 3,31 and no part of the survey has been held.

The vessel has been laid up and the Owners have furnished the usual undertaking.

The vessel is still laid up.
The year of grace expired 3,32.

It is submitted for consideration whether in view of ~~that~~ the fact that the survey is now 2 years overdue the Owners should be asked to arrange for the vessel to be generally examined.

W 4/2 only

W 4/2 only
30.3.33



© 2020

Lloyd's Register
Foundation

W 536-0147