

6th April, 1940.

1m.434.

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

4 E

VESSEL'S NAME "MAIMOA".

Rpt. Syd.

No. 17599.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Temporary repairs effected to the starboard main feed pump.

The Surveyor recommends the ^{water end} casting of this pump be renewed or permanently repaired on the vessel's return to a home port.

It is submitted the vessel is eligible to remain as classed, subject to the water-end casting of the starboard Weir's feed pump being permanently repaired or renewed on return to a home port.

Lloyd's Register
Foundation

23.5.40.

W54-0086

be made in the Register Book in the case of this vessel. Subject