

Less above Cro
Engine Room

250,7,10.

F.E.

Received by Chief Ship Surveyor *19/1/11*

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl. S.S. "Wearbridge"*

Rpt. *hwc.*

No. *59618.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. *78-03*

Depth "d" *25'-11 1/2"*

Framing: Table No. *3 page 16*

Description *Built angle as approved.*

Longitudinal No. *28090*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{9.39}{1}$

Bridge Deck Sheerstrake as per Rule.

Flat plate keel 1" less than required by the Rules but compensated for by increased thickness of adjoining strakes.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100A1 ("Steel")** as recommended.

✠ 100A1 ("Steel")

1 DR. (stl.)

WB = all DB w 123' v E + B 43' f 157' 895t. A.P.T. 30t.

FK. 6 BH. conn. Lloyds A. + C.P. P. 24' B. 91' F36'

M
R.M.
19/1/11



© 2020

Lloyd's Register
Foundation

WS45-0236

BEAMS. I