

Surveyors 11. 11. 14 " " Received from Chief Surveyors
 NAME M. S. Lompoc Report JS No. 34548

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey 1st Entry When due

+ 100 A. 1 (Steel) Carrying petroleum in bulk
 2 ^{Gr} (Stl.) Web frames, Longitudinal framing.
 WB Cell, DB u B 25', 98t. DT 47' 560t. FPT 75t. APT. 135t.
 F.K. 17 BH p^lcm. Lays a 16 P P 104' B 34' F 43'.
 Mch'y Aft.

TH 11. 11. 14
11. 11. 14

It is concluded that the propeller post
 is $10\frac{1}{2} \times 8\frac{1}{2}$ as approved, but the Surveyors
 should state if this is so.

The Surveyors should also state.
 Whether the record of part Crm
 should be recorded in the R & D

See letter
 dated 16. 11. 14
Ward



© 2021

Lloyd's Register
 Foundation

W 547 - 0265