

Vessel's Name

Highland Warrior

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel SS "HIGHLAND WARRIOR" Report

Alb

No. 40215

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

When due

Repairs effected to damage sustained by collision after launching.

* 100 A.1. (steel) "Shelter Dk with freeboard."

2 Dks (steel) & Shelter Dk. (steel)

Cell DB 383' 1730t. FRT 110t. APT 75t.

AK. 7BH to Shelter Dk. Conn. Lloyd's A.Y.C.P.

P31' F43' on Shelter Dk.

Subject to the rules
for pipes in Bulkheads
& decks being efficiently
closed.

M AEB
29-7-10

It is concluded a Dainton pump has been fitted as in
sister vessel but the Surveyors should be requested to state if this is
so & that cargo battens are fitted in the spaces not insulated, if it is not
contemplated completing the insulation now.

date

Instructions

Lloyd's Register
Foundation

IX55-0211