

12 - JAN 1934

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. Sr. "LORD ANTRIM"

Rpt.

Dub

No.

5111

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92)

Nature of Survey

The class is subject to temporarily repaired deck plate on port side of bunker tween deck being dealt with at the Owners' convenience.

The Dublin Surveyor now reports the vessel examined afloat and on account of damage through ice, temporary repairs have been effected to shell plating etc.

The Surveyor recommends the vessel be placed in dry dock for examination and permanent repairs at the first convenient opportunity.

The bunker tween deck plate referred to above has not been dealt with.

It is submitted the vessel appears worthy to remain as classed without record of survey subject as recommended and as above.

As now: subject etc.

© 2021 Lloyd's Register Foundation
W554-0776
30.12.33