

Chief Surveyors

Received from Chief Surveyors

SHIP NAME *M de 'SAN TEODORO'*

Report *Lv*

No. *101795*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/92.)

*1<sup>st</sup>* No. *3*

**SURVEY PARTLY HELD.**

*2. 33*

When proposed to be completed *within the year of grace.*

Survey held, &c.,

*To complete the survey:- See Report.*

*Subject to the sole piece of the stern frame, repaired by electric welding  
7.25 + 12.29 being specially examined at the next dry docking.*



© 2007

*16.2.33.*

Lloyd's Register

Foundation  
W559400417