


sc.k "RIGHTWAY".

20 JUL 1931

The Aberdeen Surveyor reports that through grounding damage the propeller is broken and that the engines and boilers will be lifted out of the vessel for hull repairs.

He recommends the classification to be suspended pending the examination and repairs as stated.

IT IS SUBMITTED action be deferred.

  
18.7.31.



© 2020

Lloyd's Register  
Foundation

W564-0033