

As however, it is found that the Upper Deck stringer and plating are .7m/m, and the second deck stringer and plating .6m/m, greater in thickness than indicated on the plans, it is further submitted the scantlings of the topside materials could be approved.

C.F.
[Signature]
15.3.21.
[Signature]



© 2020

Lloyd's Register
Foundation

WS54-0254 2/2