

Subject to N^o 3 plate in Shelter deck sheer and N^o 2 in
1st below (P.S.) & framing etc in way being repaired at the
Owners' convenience

11

Chief Ship Surveyor

Received from Chief Ship Surveyor

26 JUN 1940

NAME LLANISHEN Rpt. SWS No. 22437

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey DOCKING

The Swansea Surveyors report this vessel placed in
dry dock, bottom cleaned and coated, ~~repairs or renewals to~~
and minor repairs effected.

It is submitted the vessel appears worthy to remain as
classed with record of survey 6-40 as recommended subject as above

100A.I.
WITH FBD.
6-40 SWS } Subject

way
25-6-40

X It is concluded the indented plating etc, as above, has
been examined and found to remain efficient

Have Watertight Doors now been examined and found efficient? <input checked="" type="checkbox"/>	Ditto Ditto at other places ditto <input checked="" type="checkbox"/>
Have Ventilators and their Coamings been examined	Stringers, Clamps & Shells ditto <input checked="" type="checkbox"/>

3157 0138