

Received from Chief Surveyors _____

nt to Chief Surveyors _____

ESSEL'S NAME _____

Steel S.S. "NERBUDDA".

Report _____

Gls. _____

No. 32689

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)


When due _____

Nature of Survey _____

Downton pump dispensed with for the present.
 *100 A.1. (Steel) Shelter Dk. with freeboard.
 2 Dks. (Steel) & Shelter Dk. (Steel).
 Cell DB 388' 1460t. DTa 39' 1100t. FPT 125t. APT 80t.
 FK. 8 BH to Shelter Dk. pt. Cem. Lloyd's A. & C.P.
 P31', F43' on Shelter Dk.

19. 5. 19.

The Surveyors should state the thickness of poop and forecastle side plating as this has been omitted.



W571-0140

Lloyd's Register
Foundation