

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22 June 31 When handed in at Local Office 22/6/31 Port of Singapore
 No. in Survey held at Pulo Bukom Date, First Survey 7th May Last Survey 17 June 1931
 Reg. Book. 65955 on the Wood, Iron or Steel S.S. "BORELIS" (No. of Visits 4)

TONNAGE:-
 GROSS 4155
 UNDER DECK 3739
 NET 2651

Built at Middlesbro' By whom R. Bragg & Sons When 1901-5
 Owners Anglo Saxon Petroleum Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book).
 Managers Port belonging to London

Surveyed Afloat or in Dry Dock? Afloat Name of Dock at Bukom Destined Voyage
 WB=CellDBorDBa feet: u&B 28 feet; f feet
 total capacity 80 tons. FPT 70 tons; APT 22 tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4829 Port Sing.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case. 6.5.31. S. AC.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Provisional Interim Certificate for voyage Singapore to Japan with cargo of fuel oil (See Sec's letter 6th May 31)

how done:—A General examination of the vessel was made, as far as practicable, as she lay afloat with fuel oil cargo in main and summer tanks.

The peak tank, forehold, fore and after cofferdams, Pump Room, Eng. Room and boiler room spaces, and after peak tank, cleared, cleaned and examined

The main and summer tanks being full of oil cargo could not be seen but the bulkheads in the hold, fore and after cofferdams

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Framing.	R. Frames.	Floors.	Beams.	Str. Plates.	DK. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks <u>good</u>	State if Tanks have been examined inside <u>FP. AP.</u>	Dging. Plates under Sounding Pipes <u>good</u>	Copper, or Y.M. of Wood Vessels (state if on Feet) <u>good</u>
Caulking of Decks <u>"</u>	State if Tanks now tested <u>4R DB. men.</u>	Engine Room Skylights <u>"</u>	When put on, Month <u>Year</u>
Coamings <u>"</u>	Bulkheads <u>"</u>	Coal Bunkers, Open'gs, Lids, &c. <u>"</u>	Boats <u>good</u>
Beams & Fastenings <u>"</u>	Ceiling <u>"</u>	Scuppers <u>"</u>	Masts, Yards, &c. <u>"</u>
Outside Plating <u>"</u>	Cement or Asphalt (state which) <u>good</u>	Cargo Hatchways <u>"</u>	Condition, how ascertained <u>from ak</u>
Breasthooks <u>"</u>	Rudder <u>"</u>	Hatches <u>"</u>	(State if wedges removed) <u>"</u>
Transoms <u>"</u>	Steering gear and its connections <u>"</u>	Planking of Wood Vessels <u>"</u>	Sails <u>"</u>
Frames <u>"</u>	Windlass <u>"</u>	Caulking ditto <u>"</u>	Equipment letter <u>"</u>
Reverse Frames <u>"</u>	Have Pumps now been examined and found efficient? <u>"</u>	Treenails ditto <u>"</u>	Anchors, No. of <u>3B. 15. 1K.</u>
Longitudinals <u>"</u>	Have Sluice Valves now been examined and found efficient? <u>"</u>	Breasthooks & Stomson ditto <u>"</u>	Cables (state if now ranged) <u>no</u>
Transverses <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>"</u>	Timbers of Frame at openings ditto <u>"</u>	" length (on board) <u>"</u> size <u>"</u>
Floors <u>"</u>	Have Ventilators and their Coamings been examined and found efficient? <u>yes</u>	Ditto ditto at other places ditto <u>"</u>	" Rule length <u>"</u> size <u>"</u>
Keelsons <u>"</u>		Stringers, Clamps & Shells ditto <u>"</u>	Hawser & Warps <u>sufficient</u>
Stringers <u>"</u>		Salting (state if examined) ditto <u>"</u>	Standing and Running Rigging <u>good</u>
Inner Bottom Plating <u>good</u>			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pnd24, &c."

This vessel is, in my opinion, eligible to remain as now classed in the Register Book without fresh record of survey (Perm. repairs to shell plating at next S.S. equipment to complete. MB uplators to repair at SS. DB not to be used) for the intended voyage from Singapore to Osaka, Japan taking cargo of fuel oil

Survey Fee (per Section 29) <u>\$60.00</u>	Fees applied for, <u>18/6/31</u>
Special Damage or Repair Fee (if any) (per Sec. 29) <u>\$12.50</u>	Received by me. <u>19</u>
Travelling Expenses (if chargeable) <u>\$5.00</u>	
Second Surveyor's Fee (if any) <u>£</u>	

Committee's Minute

Character Assigned

FRI. 31 JUL 1931

TUE. 20 OCT 1931

Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation

UNDERTAKING CASE

W577-0136

9.

[illegible]